



## **INSPECTION REPORT**

Report Issued:	Feb 04, 2025	Inspection Result:	PARTIAL PAS	SS
----------------	--------------	--------------------	-------------	----

Permit Number: SPRMH250017 Issuance Date: Jan 10, 2025

Property Address: 322 RIVERVIEW WAY;

**Applicant:** Air Comfort, Inc.

Contractor: Deneuve Design, Inc dba Deneuve Consrt. Serv 2344 Spruce Strt Ste B

Boulder, Co 80302

To construct: Mechanical HVAC

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** 4th floor above ceiling HVAC duct work has been installed, supported and sealed correctly. Radiation dampers are installed were required. Will inspect line set pressures at later date.

## **Corrections:**

Sincerely,

Silas Ebbert Inspector sebbert@co.routt.co.us