



# INSPECTION REPORT

**Report Issued:** Feb 28, 2025

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPRMH250017

**Issuance Date:** Jan 10, 2025

**Property Address:** 322 RIVERVIEW WAY;

**Applicant:** Air Comfort, Inc.

**Contractor:** Deneuve Design, Inc dba Deneuve Consrt. Serv 2344 Spruce Strt Ste B  
Boulder, Co 80302

**To construct:** Mechanical HVAC

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Second floor above ceiling ducts and radiation dampers are installed, supported and sealed correctly. AC line sets are installed and strapped correctly. Partial approved.

**Corrections:**

Sincerely,

Silas Ebbert  
Inspector  
sebbert@co.routt.co.us