



# INSPECTION REPORT

**Report Issued:** Apr 01, 2025

**Inspection Result:** **FAILED**

**Permit Number:** SPRMH240971

**Issuance Date:** Jul 19, 2024

**Property Address:** 2305 MT WERNER CIR;

**Applicant:** Stephen Patterson

**Contractor:** TOLIN MECHANICAL SYSTEMS CO. 12005 E. 45TH AVE. DENVER, CO 80239-3111 (303) 859-0261

**To construct:** Install exhaust fan in the ski shop. This Exhaust Fan will be used to capture fumes, debris, and other related materials that get airborne as part of the Ski Tuning process, and ski tuning machine that was moved into this space. This Unit is located on the lower level at the corner of the public open covered corridor on the southeast corner.

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Rough inspection failed, final not ready for inspection. The Building Department is requesting you contact the business owner, and request they immediatly stop using this exhaust fan, and if this also then requires them to stop tuning skis due to the fact they cannot provide a safe enviornment for employees to tune skis within, then they may have to stop operations related to ski tuning until this problem is resolved.

**Corrections:**

Sincerely,



Todd Carr  
Building Official  
tcarr@co.routt.co.us