



# INSPECTION REPORT

**Report Issued:** May 16, 2025

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPRPL250611

**Issuance Date:** May 14, 2025

**Property Address:** 200 SUNDANCE CT;

**Applicant:** Shannon A Williams

**Contractor:** Mechanical Systems of Colorado 1709 Capulin Dr colorado Springs,, CO  
80910 (719) 482-0720

**To construct:** New build SFR Unit B

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Walk and talk performed to discuss DWV system.

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us