



INSPECTION REPORT

Report Issued: Aug 06, 2025

Inspection Result: PASSED

Permit Number: SPRPL250715

Issuance Date: May 29, 2025

Property Address: 202 SUNDANCE CT;

Applicant: Mechanical Systems of Colorado

Contractor: Mechanical Systems of Colorado 1709 Capulin Dr colorado Springs,, CO
80910 (719) 482-0720

To construct: New build of a condo All new plumbing

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: DWV, waterlines run to locations on approved plans. All pipes supported and protected. DWV test is good at 5psi and waterlines are good at 60psi. Hydronic tubing installed and passed test of 100psi. Approved

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us