



INSPECTION REPORT

Report Issued: Aug 15, 2025

Inspection Result: **FAILED**

Permit Number: SPREL241278

Issuance Date: Aug 27, 2024

Property Address: 1550 AMBLE DR;

Applicant: Mike Barboza

Contractor: Lakewood Electric Company 3533 Timber Mill Pkwy, Suite A Castle Rock, CO 80109

To construct: New 5-Story Condo Building with 42 Units, with underground parking garage, amenities include a fitness room and lounge on main floor.

On this day we have inspected your construction for **Electrical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Exterior recessed can directly over a garage being soaked by pressure washer operation will require replacement and reinspection. No damage to recess can observed on unrelated inspection

Corrections:

Sincerely,

Tom Cook
Electrical Plan Reviewer/Inspector
tcook@co.routt.co.us