



# INSPECTION REPORT

**Report Issued:** Aug 18, 2025

**Inspection Result:** **FAILED**

**Permit Number:** SPRPL240545

**Issuance Date:** May 17, 2024

**Property Address:** 322 RIVERVIEW WAY;

**Applicant:** Bellyache Mechanical

**Contractor:** Bellyache Mechanical PO BOX 82 Wolcott , CO 81655 (970) 470-3341

**To construct:** Building B New Plumbing install

On this day we have inspected your construction for **Plumbing Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Was not taken into unit 222 today by Denuve, inspected 219 and everything looked good in 219 minus tub spout pulling out from wall freely, please tighten this down and call for a reinspection. We could not inspect the lobby bathrooms due to the fixtures being covered for painting.

**Corrections:**

Sincerely,

Todd Carr  
Building Official  
tcarr@co.routt.co.us