



## **INSPECTION REPORT**

Report Issued:	Aug 21, 2025	Inspection Result:	PASSED
----------------	--------------	--------------------	--------

Permit Number: SPRMH251259 Issuance Date: Aug 20, 2025

**Property Address:** 202 SUNDANCE CT;

**Applicant:** Mechanical Systems of Colorado

Contractor: Mechanical Systems of Colorado 1709 Capulin Dr colorado Springs,, CO

80910 (719) 482-0720

**To construct:** 6 exhaust fan

1 boiler fan

1 whole house fan

2 gas lines

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Inline booster installed for dryer due to exceeded vent length and fan installed in foyer for continuous ventilation.

## **Corrections:**

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us