



INSPECTION REPORT

Report Issued:	Aug 21, 2025	Inspection Result:	PASSED
-	. 0 /	mapection nesult.	IAJJL

Permit Number: SPRMH251259 Issuance Date: Aug 20, 2025

Property Address: 202 SUNDANCE CT;

Applicant: Mechanical Systems of Colorado

Contractor: Mechanical Systems of Colorado 1709 Capulin Dr colorado Springs,, CO

80910 (719) 482-0720

To construct: 6 exhaust fan

1 boiler fan

1 whole house fan

2 gas lines

On this day we have inspected your construction for **Approval for Gas Service** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Gas line hooked to fireplaces and entire line retested and passed at 15psi. Approved, green tag issued.

Corrections:

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us