



INSPECTION REPORT

Report Issued: Sep 02, 2025

Inspection Result: PASSED

Permit Number: SPRRN251231

Issuance Date: Aug 26, 2025

Property Address: 124 10TH ST;

Applicant: Jessica Ostoyich

Contractor: Gratacon LLC 200 Union Blvd, Suite G12 Lakewood, CO 80228

To construct: Minor reconfiguration and renovation of north wing for HR and legal department. Includes paint, carpeting, lighting, minor door/wall modifications, and overall refresh of the space.

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: New steel stud and wood framing completed to approved plans.

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us