



INSPECTION REPORT

Report Issued: Sep 22, 2025

Inspection Result: PARTIAL PASS

Permit Number: SPREL241278

Issuance Date: Aug 27, 2024

Property Address: 1550 AMBLE DR;

Applicant: Mike Barboza

Contractor: Lakewood Electric Company 3533 Timber Mill Pkwy, Suite A Castle Rock, CO 80109

To construct: New 5-Story Condo Building with 42 Units, with underground parking garage, amenities include a fitness room and lounge on main floor.

On this day we have inspected your construction for **Electrical Underground/Under slab** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: under slab conduits that were uninspected at garage entrance approved but future installations will require inspection or concrete will need to be demolished. Water damaged can light above garage entrance has been replaced and is approved

Corrections:

Sincerely,

Tom Cook
Electrical Plan Reviewer/Inspector
tcook@co.routt.co.us