



INSPECTION REPORT

Report Issued: Sep 25, 2025

Inspection Result: PASSED

Permit Number: SPRMH251181

Issuance Date: Aug 05, 2025

Property Address: 200 SUNDANCE CT;

Applicant: Mechanical Systems of Colorado

Contractor: Mechanical Systems of Colorado 1709 Capulin Dr colorado Springs,, CO
80910 (719) 482-0720

To construct: Adding 6 exhaust fans, 1 dryer, 1 mini split with 2 heads.

On this day we have inspected your construction for **Approval for Gas Service** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Gas line extended to meter location. Gas line test is good at 15psi. Approved, New green tag issued

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us