



# INSPECTION REPORT

**Report Issued:** Sep 25, 2025

**Inspection Result:** PASSED

**Permit Number:** SPRMH251259

**Issuance Date:** Aug 20, 2025

**Property Address:** 202 SUNDANCE CT;

**Applicant:** Mechanical Systems of Colorado

**Contractor:** Mechanical Systems of Colorado 1709 Capulin Dr colorado Springs,, CO  
80910 (719) 482-0720

**To construct:** 6 exhaust fan  
1 boiler fan  
1 whole house fan  
2 gas lines

On this day we have inspected your construction for **Approval for Gas Service** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Gas line extended to meter location. Gas line test is good at 15psi. Approved, New green tag issued

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us