



## **INSPECTION REPORT**

Report Issued:	Oct 02, 2025	Inspection Result:	PARTIAL PASS
•	•	moperation negation	IANIALIAS

Permit Number: SPRRN251497 Issuance Date: Sep 30, 2025

**Property Address:** 

**Applicant:** Gavin Malia

Contractor: STEAMBOAT SKI & RESORT CORP 2305 MT. WERNER CIR STEAMBOAT SPGS,

CO 80487 (678) 863-8219

**To construct:** Project to replace the lift gates at the Wildblue Gondola and Steamboat

Gondola with a new rack system for the new gates to hang on. It will consist of sonotube pier foundations supporting a steel structure that the gates will

hang from.

On this day we have inspected your construction for **Footing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Partial Wild Blue: 3-F4.5 pads formed to proper size per approved plans. Rebar mats are properly sized and spaced.

## **Corrections:**

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us