



INSPECTION REPORT

Report Issued: Oct 10, 2025

Inspection Result: PASSED

Permit Number: SPRPL251611

Issuance Date: Oct 09, 2025

Property Address: 2700 VILLAGE DR;

Applicant: Andres Valencia Lopez

Contractor: ELK COUNTRY RENOVATIONS LLC 625 COUNTY RD CRAIG, CO 81625 (970) 326-7024

To construct: Add a washer.

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: 2 tubs replaced with showers and new washer box. Showers water tested and washer box passed test of 5psi. Waterlines are live. Approved

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us