



INSPECTION REPORT

Report Issued: Oct 17, 2025

Inspection Result: **PARTIAL PASS**

Permit Number: SPRPL251434

Issuance Date: Sep 12, 2025

Property Address: 2077 WALTON CREEK RD, UNIT:4;

Applicant: MOUNTAIN HIGH MECHANICAL

Contractor: Kocon, LLC PO Box 775735 Steamboat Springs, CO 80477 (970) 819-1983

To construct: Rough plumbing for the whole house and fixture installation.

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Partial: Underground DWV run to locations on approved plans including sewer stub. All pipe is properly bedded and passed test of 7psi. Approved

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us