



INSPECTION REPORT

Report Issued: Oct 30, 2025

Inspection Result: PASSED

Permit Number: SPRPL251731

Issuance Date: Oct 29, 2025

Property Address: 1920 BRIDGE LN, UNIT:11;

Applicant: Perfect Routt

Contractor: Perfect Routt 23800 CR 16, 301 Oak Creek, CO 80467

To construct: Inspected un permitted work, discovered improper drain serving washer box, made alteration to bring up to code.... all other un inspected work is up to code

On this day we have inspected your construction for **Plumbing Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: All fixtures are operable, caulked and leak free. Final approved.

Corrections:

Sincerely,

Silas Ebbert
Inspector
sebbert@co.routt.co.us