



## **INSPECTION REPORT**

Report Issued:	Nov 26, 2025	Inspection Result:	PASSED

Permit Number: SPRSF250158
Issuance Date: Jun 25, 2025
Property Address: 2402 CHUTES LN;

**Applicant:** FOX CONSTRUCTION

Contractor: FOX CONSTRUCTION P.O. BOX 772971 STEAMBOAT SPGS, CO 80477 (970)

879-7529

**To construct:** UNIT A of New DUPLEX: 5,698 SF with 632 SF Attached Garage. 5 Bedroom, 5.5

Bathroom

On this day we have inspected your construction for **Foundation Drain Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Drain pipe is installed and bedded correctly with correct gravel and fabric cover installed. Approved to backfill.

## **Corrections:**

Sincerely,

Silas Ebbert Inspector sebbert@co.routt.co.us