



# INSPECTION REPORT

**Report Issued:** Dec 30, 2025

**Inspection Result:** **FAILED**

**Permit Number:** SPREL241278

**Issuance Date:** Aug 27, 2024

**Property Address:** 1550 AMBLE DR;

**Applicant:** Mike Barboza

**Contractor:** Lakewood Electric Company 3533 Timber Mill Pkwy, Suite A Castle Rock, CO 80109

**To construct:** New 5-Story Condo Building with 42 Units, with underground parking garage, amenities include a fitness room and lounge on main floor.

On this day we have inspected your construction for **Electrical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Connection point for garage fan b01 in pool room considered inaccessible recall when solution found

**Corrections:**

Sincerely,

Tom Cook  
Electrical Plan Reviewer/Inspector  
tcook@co.routt.co.us