



# INSPECTION REPORT

**Report Issued:** Jan 12, 2026

**Inspection Result:** PARTIAL PASS

**Permit Number:** SPREL241278

**Issuance Date:** Aug 27, 2024

**Property Address:** 1550 AMBLE DR;

**Applicant:** Mike Barboza

**Contractor:** Lakewood Electric Company 3533 Timber Mill Pkwy, Suite A Castle Rock, CO 80109

**To construct:** New 5-Story Condo Building with 42 Units, with underground parking garage, amenities include a fitness room and lounge on main floor.

On this day we have inspected your construction for **Electrical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** partial final approved for all units on second level .Unit 208 Powder Room GFI buried. 211 missing breaker blanks in panel. Glycol pumps and pool equipment room violate working clearances for Jason equipment require 42 inches of clearance.

**Corrections:**

Sincerely,

Tom Cook  
Electrical Plan Reviewer/Inspector  
tcook@co.routt.co.us