



INSPECTION REPORT

Report Issued: Jan 30, 2026

Inspection Result: PARTIAL PASS

Permit Number: SPREL241278

Issuance Date: Aug 27, 2024

Property Address: 1550 AMBLE DR;

Applicant: Mike Barboza

Contractor: Lakewood Electric Company 3533 Timber Mill Pkwy, Suite A Castle Rock, CO 80109

To construct: New 5-Story Condo Building with 42 Units, with underground parking garage, amenities include a fitness room and lounge on main floor.

On this day we have inspected your construction for **Electrical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Rough inspection passed.

Requested working clearance corrections resolved in units 401, 402, 406, 407, 410, and 411.

Requested working clearance corrections resolved in boiler room.

Corrections:

Sincerely,

Dave Pieknik
Code Compliance Officer



dpieknik@co.routt.co.us