



## **INSPECTION REPORT**

Report Issued: Aug 23, 2021 Inspection Result: PARTIAL PASS

Permit Number: SPRMH210052 Issuance Date: Aug 19, 2021

Property Address: 2305 MT WERNER CIR;

**Contractor:** Saunders Construction, LLC 86 Inverness Place North Englewood, Co 80112

(303) 386-9140CENTRAL ELECTRIC, LLC 2659 Jacob Cir #4 STEAMBOAT SPGS,, CO 80487 (970) 846-8379MTech Mechanical Technologies Group 12300 Pecos

Street Westminster, Co 80234 (719) 782-4000

**To construct:** Install single boiler and install hydronic

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Tie into mains for lower gondola snow melt Tee's added to already tested mains 100 psi test is good OK to backfill

## **Corrections:**

Sincerely,

Don Marchbanks Inspector dmarchbanks@co.routt.co.us