



# INSPECTION REPORT

**Report Issued:** Aug 26, 2021

**Inspection Result:** PASSED

**Permit Number:** B-21-896

**Issuance Date:** Aug 10, 2021

**Property Address:** 927 OAK ST;

**Contractor:**

**To construct:** Work Description: An EV charging station will be installed in the parking lot in the rear.

On this day we have inspected your construction for **Foundation Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Footing for EV charging station has been formed and located to approved plans. All rebar is sized and spaced correctly. Approved to pour.

**Corrections:**

Sincerely,

Silas Ebbert  
Inspector  
sebbert@co.routt.co.us