



INSPECTION REPORT

| Report Issued: | Sep 03, 2021 | Inspection Result: | PARTIAL PASS |
|-------------------|--|--------------------|--------------|
| | | | |
| Permit Number: | SPRPL210192 | | |
| Issuance Date: | Sep 02, 2021 | | |
| Property Address: | 2305 MT WERNER CIR; | | |
| | | | |
| Contractor: | MTech Mechanical Technologies Group 12300 Pecos Street Westminster, Co | | |
| | 80234 (719) 782-4000 | | |
| To construct: | Boiler Plant & Goldwalk p | lumbing UG and AG | |

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Inspected 09/02 for floor sink and vent in mechanical room 5.5 psi test is good OK to backfill pipe

Corrections:

Sincerely,

Don Marchbanks Inspector dmarchbanks@co.routt.co.us