



INSPECTION REPORT

Report Issued: Aug 20, 2021

Inspection Result:

PARTIAL PASS

Permit Number: SPRMH210052

Issuance Date: Aug 19, 2021

Property Address: 2305 MT WERNER CIR;

Contractor: Saunders Construction, LLC 86 Inverness Place North Englewood, Co 80112 (303) 386-9140 CENTRAL ELECTRIC, LLC 2659 Jacob Cir #4 STEAMBOAT SPGS,, CO 80487 (970) 846-8379 MTech Mechanical Technologies Group 12300 Pecos Street Westminster, Co 80234 (719) 782-4000

To construct: Install single boiler and install hydronic

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Hydronic pipe mains for snow melt Test gauge in horseshoe foundation and other in mechanical room 98 psi test on both is good Pipe and pipe insulation is good OK to backfill Will need to retest when additional pipe is added

Corrections:

Sincerely,

Don Marchbanks
Inspector
dmarchbanks@co.routt.co.us