



## **INSPECTION REPORT**

Report Issued:	Sep 13, 2021	Inspection Result:	PARTIAL PASS
Permit Number: Issuance Date: Property Address:	• •		
Contractor:	Saunders Construction, LL (408) 656-9910	C 86 Inverness Place North	Englewood, CO 80112
To construct:	Work Description: Relocate existing gondola terminal to the base of the ski mountain. Lift and Operator Cabin by lift provider and to be reviewed by Colorado Tram Board. Provide platform for queue and Elevator/Boiler building for ADA access and snowmelt.		
	Total Project Valuation = \$ BedroomsNoEx: 0 BedroomsNoProp: 0 HeightofConstructionEx: 0 HeightofConstructionProp LivingAreaEx: 0.00 LivingAreaProp: 0.00 SignLength: 0.00 SignWidth: 0.00 StoriesNoEx: 0 StoriesNoProp: 0	.00	

On this day we have inspected your construction for **Foundation Drain Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

TotalAreaEx: 0.00 TotalAreaProp: 0.00

**Comments:** Foundation drain pipe gravel and marifi is good around perimeter of foundation OK





to finish tie in to main and backfill

**Corrections:** 

Sincerely,

Don Marchbanks Inspector dmarchbanks@co.routt.co.us