



INSPECTION REPORT

Report Issued: Sep 17, 2021

Inspection Result: PARTIAL PASS

Permit Number: SPRMH210082

Issuance Date: Aug 23, 2021

Property Address: 2305 MT WERNER CIR;

Contractor: Deans Plumbing and Heating Inc 192 East Line Street Bishop , CA 93514
To construct: Installing underground mains,insulation,tubing,manifolds,above ground piping,and pumps to be connected to the flat plate heat exchanger in the mechanical room for the snowmelt system.

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Underground snow melt mains on existing promemnade area Tee's and welded connections will stay exposed OK to backfill

Corrections:

Sincerely,

Don Marchbanks
Inspector
dmarchbanks@co.routt.co.us