



INSPECTION REPORT

Report Issued: Sep 10, 2021

Inspection Result: PARTIAL PASS

Permit Number: SPRMH210052

Issuance Date: Aug 19, 2021

Property Address: 2305 MT WERNER CIR;

Contractor: Saunders Construction, LLC 86 Inverness Place North Englewood, CO 80112 (408) 656-9910 CENTRAL ELECTRIC, LLC 2659 Jacob Cir #4 STEAMBOAT SPGS,, CO 80487 (970) 846-8379 MTech Mechanical Technologies Group 12300 Pecos Street Westminster, Co 80234 (719) 782-4000

To construct: Install single boiler and install hydronic

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Hydronic pipe with 100 psi test is good Under slab heat in horse shoe area Insulation is good

Corrections:

Sincerely,

Don Marchbanks
Inspector
dmarchbanks@co.routt.co.us