



INSPECTION REPORT

Report Issued: Oct 19, 2021

Inspection Result: PARTIAL PASS

Permit Number: SPRMH210083

Issuance Date: Aug 23, 2021

Property Address: 2305 MT WERNER CIR;

Contractor: Deans Plumbing and Heating Inc 192 East Line Street Bishop , CA 93514
To construct: Installing underground mains,insulation,tubing,manifolds,above ground piping,and pumps to be connected to the flat plate heat exchanger in the mechanical room for the snowmelt system.

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: hydronic main lines under the 2 foot foam build up at the top of the Goldwalk escalator approved held 100 psi for 15 minutes, additional inspections needed to the west of where the last box is installed, main lines capped about 15 west of the 2nd box from the top of the escalator.

Corrections:

Sincerely,

Todd Carr
Building Official
tcarr@co.routt.co.us