



INSPECTION REPORT

Report Issued: Nov 01, 2021

Inspection Result:

PARTIAL PASS

Permit Number: SPRMH210082

Issuance Date: Aug 23, 2021

Property Address: 2305 MT WERNER CIR;

Contractor: Deans Plumbing and Heating Inc 192 East Line Street Bishop , CA 93514
To construct: Installing underground mains,insulation,tubing,manifolds,above ground piping,and pumps to be connected to the flat plate heat exchanger in the mechanical room for the snowmelt system.

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: hydronic piping held 100 psi for 15 minutes r 5.6 below and tubes space per plans, approved for sidewalk leading to restrooms off promenade, restrooms under stage, also approved main promenade area in front of lower terminal to from F & B line to existing that was not disturbed, also approved remainder of main promenade square up until crane canopy location.

Corrections:

Sincerely,

Todd Carr
Building Official
tcarr@co.routt.co.us