



## **INSPECTION REPORT**

Report Issued:	Nov 01, 2021	Inspection Result:	PARTIAL PASS
Permit Number: Issuance Date: Property Address:	SPRMH210083 Aug 23, 2021 2305 MT WERNER CIR;		
Contractor: To construct:	Deans Plumbing and Heatin Installing underground ma piping, and pumps to be commechanical room for the sr	ins,insulation,tubing,mani nnected to the flat plate he	folds,above ground
On this day we have inspected your construction for <b>Mechanical Rough-in Inspection</b> and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.			
<b>Comments:</b> hydronic tubing held 100 psi with R5.6 under and tubes spaced per plans on entire top area above escalator			
Corrections:			
Sincerely,			
Todd Carr Building Official tcarr@co.routt.co.us			