



# INSPECTION REPORT

**Report Issued:** Dec 21, 2021

**Inspection Result:** PASSED

**Permit Number:** B-21-347

**Issuance Date:** Apr 20, 2021

**Property Address:** 2305 MT WERNER CIR;

**Applicant:** Josh Boh

**Contractor:** Saunders Construction, LLC 86 Inverness Place North Englewood, CO 80112  
(408) 656-9910

**To construct:** Work Description: WORK TO INCLUDE SELECT DEMOLITION OF PARTITIONS,  
CEILINGS, FINISH  
MECHANICAL, ELECTRICAL, PLUMBING & FIRE PROTECTION AS INDICATED ON  
DRAWINGS

BedroomsNoEx: 0

BedroomsNoProp: 0

HeightofConstructionEx: 0.00

HeightofConstructionProp: 0.00

LivingAreaEx: 0.00

LivingAreaProp: 0.00

SignLength: 0.00

SignWidth: 0.00

StoriesNoEx: 0

StoriesNoProp: 0

TotalAreaEx: 0.00

TotalAreaProp: 0.00

On this day we have inspected your construction for **Demolition Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** All work completed



**Corrections:**

Sincerely,

Todd Carr  
Building Official  
tcarr@co.routt.co.us