



INSPECTION REPORT

Report Issued: Apr 26, 2022

Inspection Result: **FAILED**

Permit Number: SPRSW210257

Issuance Date:

Property Address: 2305 MT WERNER CIR;

Applicant: Saunders Construction, LLC

Contractor:

To construct: Wild Blue Gondola

On April 22, 2022 we have inspected your construction project for **45 Day Inspection** and find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments:

Corrections:

- 1 Install additional rocks socks immediately to increase capacity and filtration at inlet across from old Preview Lift. Once completed email photos of corrections to Scott Slamal.

Sincerely,

Scott Slamal
Stormwater Inspector
sslamal@steamboatsprings.net

P.O. Box 775088, Steamboat Springs, Colorado 80477-5088
970.879.2060 ☎ 970.879.8851 (fax) ☎ steamboatsprings.net