



## **INSPECTION REPORT**

| Report Issued:    | Apr 29, 2022 Insi        | pection Result:    | PASSED               |
|-------------------|--------------------------|--------------------|----------------------|
| •                 |                          |                    | 17.0020              |
|                   |                          |                    |                      |
| Permit Number:    | SPRMH220489              |                    |                      |
| Issuance Date:    | Apr 28, 2022             |                    |                      |
| Property Address: | 1863 RIVER QUEEN LN;     |                    |                      |
| Applicant:        | MOUNTAIN HIGH MECHANICAL |                    |                      |
| Contractor:       | MOUNTAIN HIGH MECHANICAL | 6080 W 91ST CRT #2 | -104 WESTMINSTER, CO |
|                   | 80021 (970) 819-2690     |                    |                      |
| To construct:     | Venting new fireplaces.  |                    |                      |

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** 2 fireplace units inspected. unit in master bedroom is installed and vented to Manufactures Specs with proper clearances. Unit in great room need draft stopping installed at top of chase and framing needs to changed to create proper clearances from combustibles. Partial approved.

## **Corrections:**

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us