



# INSPECTION REPORT

**Report Issued:** May 04, 2022

**Inspection Result:** PASSED

**Permit Number:** SPRPL220364

**Issuance Date:** Apr 11, 2022

**Property Address:** 2305 APRES SKI WAY; 2305 APRES SKI WAY, UNIT:221;

**Applicant:** LEVI DOES IT

**Contractor:** McHugh Tile & Stone LLC 161 Satum DR #1B Fort Collins, CO 80525 (970) 797-6791

**To construct:** remove copper pipe and replace with pex

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** 2 shower pans installed and sealed in lower level. Both pans held water for test duration. Approved

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us