



# INSPECTION REPORT

**Report Issued:** May 25, 2022

**Inspection Result:** PASSED

**Permit Number:** SPRRN220230

**Issuance Date:** Mar 25, 2022

**Property Address:** 2305 APRES SKI WAY, UNIT:221;

**Applicant:** McHugh Tile & Stone LLC

**Contractor:** McHugh Tile & Stone LLC 161 Satum DR #1B Fort Collins, CO 80525 (970) 797-6791

**To construct:** Replacing copper water lines through out unit with new pex water lines. Remodeling 3 bathrooms with in existing footprint. Converting 2 tubs to showers.

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** All work completed to scope of permit. Approved

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us