



INSPECTION REPORT

Report Issued: May 26, 2022

Inspection Result: PASSED

Permit Number: B-21-896

Issuance Date: Aug 10, 2021

Property Address: 927 OAK ST;

Applicant: Brian Ashley Brian Ashley

Contractor:

To construct: Work Description: An EV charging station will be installed in the parking lot in the rear.

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: 1 EV Charging station completed to Approved plans. Final approved

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us