



# INSPECTION REPORT

**Report Issued:** Jul 07, 2022

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPRPL220733

**Issuance Date:** Jun 06, 2022

**Property Address:**

**Applicant:** Mechanical & Piping Inc

**Contractor:** Mechanical & Piping Inc 6440 E. 50th Ave Commerce City, CO 80022 (303) 710-2869

**To construct:** New Restaurant and Rest room, Wild Blue Gondola Mid Mountain.

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** PARTIAL: Under slab DWV run for sprung structure and matches plans on site. DWV test is good at 5.5psi. all fixtures and vents accounted for. Will inspect grease lines at next inspection.

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us