



INSPECTION REPORT

Report Issued: Aug 15, 2022

Inspection Result: **FAILED**

Permit Number: TB-21-865

Issuance Date: Aug 31, 2021

Property Address: 1863 RIVER QUEEN LN;

Applicant: Srdjan Brstina

Contractor: Brstina LLC P.O. BOX 883321 STEAMBOAT SPGS, CO 80488 (970) 846-4030

To construct: Construct single family residence

On this day we have inspected your construction for **Final Site Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Contact Scott Slamal once swale is installed and ready for final inspection.

Corrections:

- 1 Install drainage swale on back portion of lot to redirect flows to the north away from neighboring downstream property. Install silt fence at toe of disturbed soil. Be sure to trench in silt fence properly and stake.

Sincerely,

Scott Slamal
Stormwater Inspector
sslamal@steamboatsprings.net