



INSPECTION REPORT

Report Issued:	Sep 01, 2022	Inspection Result:	PARTIAL PASS
Permit Number:	SPRMH210082		
Issuance Date:	Aug 23, 2021		
Property Address:	2305 MT WERNER CIR;		
Applicant:	Deans Plumbing and Heating Inc		
Contractor:	Deans Plumbing and Heating Inc 192 East Line Street Bishop , CA 93514		
To construct:	Installing underground mains, insulation, tubing, manifolds, above ground		
	piping,and pumps to be connected to the flat plate heat exchanger in the mechanical room for the snowmelt system.		

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Balance of snowmelt tubing for place installed and properly fastened to wire mesh tubing connect to manifold on east end of rink. Tubing passed test of 100psi. Approved. Will inspect mains at later inspection.

Corrections:

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us