



INSPECTION REPORT

Report Issued: Sep 15, 2022

Inspection Result: PASSED

Permit Number: SPRPL221299

Issuance Date: Sep 13, 2022

Property Address: 2320 SKI TRAIL LN;

Applicant: Jonathan Hayek

Contractor:

To construct: Replace 2 shower valves and add ice box for fridge in kitchen

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Water line for ice maker and new lines to shower valve, connected to existing, holding under live pressure.

Corrections:

Sincerely,

Jeff Yeiser
Inspector
jyeiser@co.routt.co.us