



# INSPECTION REPORT

**Report Issued:** Sep 29, 2022

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPREL221427

**Issuance Date:** Sep 28, 2022

**Property Address:** 2305 MT WERNER CIR;

**Applicant:** CURRENT ELECTRICAL CONT.

**Contractor:** CURRENT ELECTRICAL CONT. 28395 cr 18 steamboat, CO 80487 (970) 846-1970

**To construct:** Green horn ranch chairlift and magic carpits on ski mtn.

On this day we have inspected your construction for **Electrical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Underground for electrical service lift shack and three feeders running to vaults for magic carpets approved

**Corrections:**

Sincerely,

Tom Cook  
Electrical Plan Reviewer/Inspector  
tcook@co.routt.co.us