



# INSPECTION REPORT

**Report Issued:** Oct 03, 2022

**Inspection Result:** PARTIAL PASS

**Permit Number:** SPRPL220733

**Issuance Date:** Jun 06, 2022

**Property Address:**

**Applicant:** Mechanical & Piping Inc

**Contractor:** Mechanical & Piping Inc 6440 E. 50th Ave Commerce City, CO 80022 (303) 710-2869

**To construct:** New Restaurant and Rest room, Wild Blue Gondola Mid Mountain.

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Gas line previously inspected for underground install from storage building below up to sprung structure, now air is applied from storage building to sprung structure, then in through east wall then upstairs to mechanical platform up to where future appliance connections can be made, all held 20 psi for 15 minutes. Gas line had conduit sweeps and tracer wire visible as it entered and exited ground on both ends. Sprung structure penetration sleeve used to enter building. gas pipe supported properly on mechanical decking.

DWV approved for short section of vent pipe on top of mechanical platform only, held 5 psi for 15 minutes and supported properly.

**Corrections:**

Sincerely,

Todd Carr



Building Official  
tcarr@co.routt.co.us