



INSPECTION REPORT

Report Issued: Oct 05, 2022

Inspection Result: **FAILED**

Permit Number: SPRSW210257

Issuance Date:

Property Address: 2305 MT WERNER CIR;

Applicant: Saunders Construction, LLC

Contractor:

To construct: Gondola Relocation Project

On this day we have inspected your construction for **45 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Send photos of inlet protection once completed.

Corrections:

- 1 Install inlet protection at newly installed inlet at base of wild blue gondola terminal.

Sincerely,

Scott Slamal
Stormwater Inspector
sslamal@steamboatsprings.net