

INSPECTION REPORT

Report Issued: Oct 06, 2022 Inspection Result: FAILED

Permit Number: SPRSW221187 Issuance Date: Aug 19, 2022

Property Address: 1851 RIVER QUEEN LN;

Applicant: Vaussa Custom Contracting

Contractor:

To construct: new single family house

On this day we have inspected your construction for **45 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments:

Corrections:

1 Please install silt fence at toe of excavation and email me photos once completed. Please have this done by Wednesday next week.

Sincerely,

Scott Slamal Stormwater Inspector sslamal@steamboatsprings.net