



INSPECTION REPORT

Report Issued:	Oct 14, 2022	Inspection Result:	PASSED
ricport issucu.	000 1 1, 2022	ilispection result.	PASSEI

Permit Number: SPREL221498
Issuance Date: Oct 10, 2022

Property Address:

Applicant: STEAMBOAT SKI & RESORT CORP

Contractor:

To construct: wire Bashor Block house and replace electrical disconnect and wires

On this day we have inspected your construction for **Electrical Temp Service** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Repairs to service complete and approved

Corrections:

Sincerely,

Tom Cook
Electrical Plan Reviewer/Inspector
tcook@co.routt.co.us